

HARTZELL

# PROPELLER LOGBOOK

PROPELLER MODEL PHC-13MF-1N

PROPELLER S/N N1517B

N881CA

LOGBOOK # \_\_\_\_\_

PROPELLER MAINTENANCE RECORD

Position ONE

Propeller Model PHC-J3YIF-

Propeller S/N N3517B

Blade Design N7605B

Blade S/N's

No. 1 A5430

No. 2 A5441

No. 3 A5445

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

No. 6 \_\_\_\_\_

Spinner Assembly Part No. \_\_\_\_\_

PITCH RANGE

High/Feather \_\_\_\_\_

Start Lock \_\_\_\_\_

Low \_\_\_\_\_

Reverse \_\_\_\_\_

Model TS02761

Engine Preheater

This Tanis Aircraft engine preheater is manufactured under FAA-PMA and is eligible by that approval on the following engines:

TSIO-550-K, IO-550-N, IO-550-R







Date	Propeller		A/C Hrs	Description of Work pertaining to Airworthiness Directives, Service Bulletins, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				<p><b>EPPS Aviation</b></p> <p>AIRCRAFT REG: N881CA MFG: Hartzell MODEL: PHC-J3Y1F-1N SERIAL: NJ517B HOUR METER: 433.6</p> <p>DATE: 17-Apr-2017 WORK PACKAGE: P6265 TACH TIME: 350.1 TOTAL TIME: 350.1 TSMOH: 0.00</p> <p>Completed 100HR and service referencing Far 43 App D checklist.</p> <p>The aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under work package no. <b>P6265</b>.</p> <p>Signed: <i>Steve Taylor</i> STEVE TAYLOR for Epps Air Service, Inc., ESMR688D, 1 Aviation Way, Atlanta, GA 30341</p> <p>Page 1 of 1</p>

Date	Propeller		A/C Hrs	Description of Work pertaining to Airworthiness Directives, Service Bulletins, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				<p><b>EPPS Aviation</b></p> <p>AIRCRAFT REG: N881CA MFG: Hartzell MODEL: PHC-J3Y1F-1N SERIAL: NJ517B HOUR METER: 510.1</p> <p>DATE: 03-May-2018 WORK PACKAGE: P6767 TACH TIME: 415.1 TOTAL TIME: 415.1 TSMOH: 0.00</p> <p>Performed 100 hour inspection of propeller on this Propeller Assembly. Propeller and attaching components have been found to be in satisfactory condition at this time.</p> <p>The aircraft, airframe, engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under work package no. <b>P6767</b>.</p> <p>Signed: <i>Joe Jordan</i> JOE JORDAN for Epps Air Service, Inc., ESMR688D, 1 Aviation Way, Atlanta, GA 30341</p> <p>Page 1 of 1</p>









Date	Propeller		A/C Hrs
	TSN	TSO	


all operations pertaining to Airworthiness Directives,  
 Alerts, Overhaul, Major or Minor Repair, and Inspections.

Sunstate Propeller, Inc  
 800 43RD Street South, St. Petersburg Fl. 33711  
 1-800-226-1089  
**PROPELLER WAS OVERHAULED**  
 MODEL: PHC-J3Y1F-1N  
 SERIAL: NJ517B Completed on this  
 Date: 06/01/2023 and was returned to service  
 under work order # 19282

Signature  CRS#OW4R429M

Sunstate Propeller, Inc  
 800 43RD Street South, St. Petersburg Fl. 33711  
 1-800-226-1089  
**GOVERNOR WAS OVERHAULED**  
 MODEL: S-1-44F  
 SERIAL: G697NJ Completed on this  
 Date: 06/06/2023 and was returned to service  
 under work order # 19289

Signature  CRS# OW4R429M

4701 NE 40th Terrace  
 Gainesville, FL 32609  
 United States

June 09, 2023

Manufacturer: HARTZELL PROPELLER	Telephone: 352-416-8039
Part/Model number: PHC-J3Y1F-1N	TSN/TSO: 1,785.10 / 0.00
Work Order No: 1914	Tech/ Hobbs: 1765, U/145.7
	Serial Number: N01179
	Date: 06/09/2023

**Squawk**

3.1 Performed Annual inspection and servicing of propeller per 14 CFR 43 Appendix D and with reference to the Cirrus SR22T AMM and Hartzell owner manual.

3.2 Removed propeller for overhaul by Sunstate propellers. Reinstalled propeller Model PHC-J3Y1F-1N S/N/NJ517B. Referenced to Cirrus SR22T AMM and Hartzell Propeller Owners Manual.

3.3 Removed propeller Governor Model S-1-44F S/N G697NJ for overhaul by Sunstate Propellers. Installed governor, ops check and leak check good at this time. Referred to Hartzell Propeller Owners Manual and Continental Standard Practice Manual M-0.

3.4 Performed Research of Maintenance Records and found all applicable ADs in complied with at this time. Found manufacturer service bulletins complied with at this time.

These items identified above were repaired and/or inspected in accordance with current Federal Aviation Regulations and the repairs are approved for return to service.

Tyler Abo ASP-4149522 1A 