


N 759 B Z



mt-propeller

The Winner's Propeller

PROPELLER LOGBOOK

EASA DE.21G.0008 / EASA.21J.020

MTE - 1198
Juni 2005

Owner Name _____

Address _____

Propeller Model MTV-15-D

Blade Model 270-58

Hub Serial No. 187303

Blade Serial No. 1 AJH-72235 Propeller Diameter: 270 cm ± 9.5 cm

2 AJH-72236 Low Pitch: 7.5 ° ± 0.2 ° TCI: 72 Month

3 / High Pitch: 33 ° ± 1 ° TBO: 1800 Hrs.

4 / Feathering: / ° ± / °


5 / Reverse: / ° ± / °

6 / at radius station: 79 cm

INSTALLATION HISTORY

Date	Aircraft Model, Registration & Serial No., Tacho or Hobbs-Time
7-05-19	Installed on Cessna N 7593Z, S/N 18265825
	TACH: 2823.5
	- Prop - MTV-15-D/210-58 S/N 181303

MAINTENANCE & SERVICE HISTORY

Date	Total Propeller Time	Time Since Overhaul	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Nov-07 2018	00:00	-	Manufactured	

DATE: 07/05/2019

N: N 759BZ

TACH: 2823.5


PROP: MT propeller MTV-15-D/210-58 S/N: 181303

TSNEW: 0.0

Completed Annual inspection. Removed propeller Hartzell BHC-G2YF-1BF S/N JH1348. Installed new MT-propeller model MTV-15-D/210-58 S/N 181303, in accordance with STC. Inspect blades, hub, spinner and bulkheads..

I certify that this **PROPELLER** has been inspected in accordance with an **ANNUAL** inspection and was determined to be in an Airworthy Condition.

Larry Hallock
IA 2239535



Professional Aircraft Services
4824 Earhart Rd, Loveland, CO 80538
970-679-4633

MAINTENANCE & SERVICE HISTORY


Log Book Entry
Propeller- 100 Hour and Annual Inspection

Reg: N759BZ
Date: 5/**/21

Model: MTV-15D/21058
Tach: 2938.7

S/N: 18103
PTSN: 115.2

Performed an Annual Inspection with reference to FAR Part 43, Appendix D. Checklist as a guide only. Complied with all AD's thru 2021-10. Safetied Two Propeller Spinner Inner Aft Attach Bolts as required. I certify this propeller has been inspected/repared with reference to an Annual Inspection and has been determined to be in an airworthy condition and that work described above was accomplished and inspected in accordance with current FAA regulations and is approved for return to service. -END-



David A. Johnson, 3638866, A&PTA

--	--	--	--	--

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12

MAINTENANCE & SERVICE HISTORY

Date	Time	Description Of Work	Authorized Signatures Repairman and Station Certificate Numbers
Inspected	Time	Description Of Work	Authorized Signatures
Inspection	Time	Description Of Work	Authorized Signatures
Tach read	Time	Description Of Work	Authorized Signatures
SIGNED	Time	Description Of Work	Authorized Signatures

Dramstad Flying Service 3080 Airport Rd Helena, MT 59601 406-443-0066

09-01-2023 N759BZ Tach Time: 2967.8 PTSN: 144.3

I certify this propeller has been inspected in accordance with a 100 hour inspection and was determined to be in an airworthy condition.

Jerry Gresens AP 3395269

NOTE: Enter Compliance With All Applicable FAA A.D. & Factory Service Bulletins On Pages 11 & 12